

F | G. 2






FIG. 3



F I G. 4



BEST AVAILABLE COPY

FIG. 5




FIG. 6

	Washing	Drying1	Drying 2	Drying 3
HF Dip				
MIQ				
DIW water-saving				
Slow up Speed				
Purge N2				
Quick Drain				
Porous plate IN				
IPAsupply			N ₂	
Dry N2			2 -	

F I G. 7




FIG. 8




FIG. 9

